## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6,808,612 B2

Page 1 of 1

DATED

: October 26, 2004

DATED

INVENTOR(S) : Peter Hey and Byung-Sung Leo Kwak

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## Title page,

Item [56], References Cited, FOREIGN PATENT DOCUMENTS, add -- DE 932 709 --.

## Column 11,

Line 59, add -- a -- after "into".

Line 63, change "20 mA\*sec/cm<sub>2</sub>" to -- 20 mA\*sec/cm<sup>2</sup> --.

## Column 12,

Line 23, add -- a -- after "plating".

Signed and Sealed this

Twenty-eighth Day of June, 2005

JON W. DUDAS
Director of the United States Patent and Trademark Office